


WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. Street City Zip 754 - 921 Thomas Lane - Springville, AL 35146	Date of Inspection 02/14/2012	Number of Pages 1 / 5
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="width: 30%;"> <p>EasyBee Software (Image) 642 Cross Street Springville, AL 35146</p> <p>Size: 800 x 150 pixels - Filename: WdoStyle3.jpg</p> </div> <div style="width: 40%; text-align: center;"> <p>ProWDO <i>Structural Pest Control Report Solutions</i></p> <p>Office: 205.467.7427 - Toll Free 877.903.6176</p> </div> <div style="width: 20%; text-align: center;"> </div> </div>		Report # 00000004
		Lic Registration REG-0699473
		Escrow #
Ordered By: Killer Realty, Inc. 485 Southview Drive Birmingham, AL 35773	Property Owner and/or Party of Interest: Killer Realty, Inc. 485 Southview Drive Birmingham, AL 35773	Report Sent To: Killer Realty, Inc. 485 Southview Drive Birmingham, AL 35773
Complete Report <input checked="" type="checkbox"/> Limited Report <input type="checkbox"/> Supplemental Report <input type="checkbox"/> Reinspection Report <input type="checkbox"/>		
General Description: Half basement, split level		Inspection Tag Posted: Front Other Tags Posted: Back Door
An inspection has been made of the structure(s) shown on the diafram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.		
Subterranean Termites <input checked="" type="checkbox"/> Drywood Termites <input type="checkbox"/> Fungus / Dryrot <input type="checkbox"/> Other Findings <input type="checkbox"/> Further Inspection <input type="checkbox"/>		
If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.		



This diagram is not to scale

Inspected By: Kenny Brownlee **State License No.:** ST-049967 **Signature:** _____

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 1418 Howe Avenue, Suite 18, Sacramento, California, 95825-3204.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916)561-8708, (800)737-8188 or www.pestboard.ca.gov